# Evaluation of Candidate Stirling Engine Heater Tube Alloys After 3500 Hours Exposure to High Pressure Doped Hydrogen or Helium

John A. Misencik and Robert H. Titran National Aeronautics and Space Administration Lewis Research Center

October 1984

Work performed for
U.S. DEPARTMENT OF ENERGY
Conservation and Renewable Energy
Office of Vehicle and Energy R&D
Washington, D.C. 20545
Under Interagency Agreement DE-Al01-77CS51040

# Evaluation of Candidate Stirling Engine Heater Tube Alloys After 3500 Hours Exposure to High Pressure Doped Hydrogen or Helium

John A. Misencik and Robert H. Titran National Aeronautics and Space Administration Lewis Research Center

October 1984

Work performed for U.S. DEPARTMENT OF ENERGY Conservation and Renewable Energy Office of Vehicle and Energy R&D Washington, D.C. 20545 Under Interagency Agreement DE-Al01-77CS51040

# EVALUATION OF CANDIDATE STIRLING ENGINE HEATER TUBE ALLOYS AFTER 3500 HOURS EXPOSURE TO HIGH PRESSURE DOPED HYDROGEN OR HELIUM

John A. Misencik and Robert H. Titran National Aeronautics and Space Administration Lewis Research Center Cleveland, Ohio 44135

#### SUMMARY

Sixteen commercial tubing alloys were endurance tested in a diesel-fuel fired Stirling engine simulator materials test rig. The objective of the tests were to evaluate the endurance limits of sixteen alloys (up to 3500 hr at 15 MPa pressure at 820°C) and select one alloy for further testing at a higher pressure of 21 MPa. During exposure, two sets of each alloy in the form of thin-wall tubing, "hairpin tubes" were pressurized -- one with hydrogen doped with 1.0 vol % CO<sub>2</sub> and the other with helium. The alloys tested were: iron-base N-155, A-286, Incoloy 800, 19-9DL, CG-27, W-545, 12RN72, 253MA, Sanicro 31H and Sanicro 32; nickel-base Inconel 601, Inconel 625, Inconel 718, Inconel 750 and Pyromet 901; and cobalt-base HS-188.

The iron-nickel alloys CG-27 and Pyromet 901 exhibited superior oxidation/corrosion resistance to the diesel-fuel combustion products and surpassed the design criterias' 3500 hr creep-rupture endurance life. Three other alloys, Inconel 625, W-545, and 12RN72, which are considered to have performed well, had creep-rupture failures after 2856, 2777, and 1598 hr, respectively. Hydrogen permeability coefficients determined after 250 hr of rig exposure show that Pyromet 901 had the lowest  $\phi$  value,  $0.064 \times 10^{-6}$  cm²/sec MPa¹/². The next five hairpin tubes, CG-27, Inconel 601, Inconel 718(wd), Inconel 750, and 12RN72(cw) all had  $\phi$  values below  $0.2 \times 10^{-6}$  more than a decade lower than the design criteria. Based upon its measured high strength and low hydrogen permeation, CG-27 was selected for 3500 hr endurance testing at 21 MPa gas pressure and 820° C.

The results of the high pressure, 21 MPa, CG-27 endurance test demonstrated that the 1.0 vol %  $\rm CO_2$  dopant is an effective deterrent to hydrogen permeation. The 21 MPa hydrogen gas pressure apparent permeability coefficient at 820° C approached  $0.1 \times 10^{-6}$  cm<sup>2</sup>/sec MPa<sup>1/2</sup> after 500 hr, the same as the 15 MPa test. Even at this higher gas pressure and comparable permeation rate, CG-27 passed the 3500 hr endurance test without creep-rupture failures. It is concluded that the CG-27 alloy, in the form of thin wall tubing is suitable for Stirling engine applications at 820° C and gas pressures up to 21 MPa.

#### INTRODUCTION

The work described in this report was conducted as part of the continuing supporting research and technology activities under the DOE-NASA Stirling Engine Highway Vehicle Systems Program (ref. 1). To achieve maximum efficiency in the Stirling Engine, hydrogen is used as the working fluid and operating temperatures are high, near 870° C in some proposed engine designs. In current prototype engines, N-155, an alloy containing 20 percent cobalt is used

for the heater head tubing. Because of the strategic nature of cobalt (greater than 90 percent import dependence by the United States), its limited availability compared to the mass market needs for proposed automotive Stirling engine applications, and high-cost, alloys containing cobalt cannot be considered for automotive applications (ref. 2).

Planned automotive applications of the Stirling engine require cyclic on off operation with resulting temperatures of the heater head tubes ranging from room temperature to near 900° C (ref. 3). In addition, speed of the automobile is controlled by pressure variation of the hydrogen working fluid contained in the heater head tubes. Pressure normally ranges between 2 and 15 MPa with an average pressure near 7 MPa based on a 50 percent urban/50 percent highway driving cycle.

Two Stirling engine simulator rigs have been fabricated and are being used at NASA LeRC to evaluate candidate Stirling engine heater tube alloys under simulated conditions of cyclic temperatures, hydrogen pressure, and dieselfuel combustion gas environment. To date, five endurance runs (refs. 4 and 5) and two hydrogen dopant studies (refs. 6 and 7) have been completed using the NASA LeRC Stirling engine simulator test rigs. The first was an endurance run for 1000 hr at 760° C and 21 MPa hydrogen pressure, using pure and commercial hydrogen (ref. 4), the second was an endurance run for 535 hr at 860° C and 21 MPa hydrogen pressure, using commercial hydrogen. The third was an endurance run for 1000 hr at 820° C and 21 MPa hydrogen pressure, using commercial hydrogen (ref. 5), the fourth was an endurance run for 3500 hr at 820° C and 15 MPa hydrogen pressure, using hydrogen doped with 1.0 vol % carbon dioxide, and the fifth was an endurance run for 3500 hr at 820° C and 21 MPa hydrogen pressure using the best alloy from the previous 3500 hr run. This was also conducted using hydrogen doped with 1.0 vol % carbon dioxide. The results of the fourth and fifth endurance runs (3500 hr) will be discussed in this report.

The purpose of this investigation was three-fold: (1) to rank the candidate Stirling engine heater tube alloys according to their endurance limits in the Stirling engine simulator rig at 820° C and 15 MPa pressure; (2) to rank candidate heater tube alloys as to their ability to contain hydrogen at 820° C; and (3) to select and endurance test the best alloy at 21.6 MPa hydrogen pressure and 820° C temperature.

The alloys evaluated included N-155, and 15 other candidate heater tube alloys under conditions of cyclic temperature, pressure, and environment (hydrogen and combustion products) that simulate the actual operation of a Stirling powered highway vehicle. The alloys tested included 10 iron-base alloys, N-155, A-286, Incoloy 800, 19-9DL, CG-27, W-545, 12RN72, 253MA, Sanicro 31H, and Sanicro 32; five nickel base alloys Inconel 601, Inconel 625, Inconel 718, Inconel 750 and Pyromet 901; and one cobalt-base alloy HS-188. The iron-base and nickel-base alloys are considered possible candidates for the Stirling engine heater tubes. Six of the alloys were evaluated previously in endurance runs at 760°, 820°, and 860° C. These alloys were N-155, A-286, Incoloy 800, 19-9DL, Inconel 718 and HS-188. The results obtained in these endurance runs are reported in references 4 and 5.

#### EXPERIMENTAL PROCEDURES

#### Materials

The alloys used in this study were obtained commercially in the form of tubing. Two sizes were studied, one with an outside diameter of 4.8 mm and inside diameter of 3.2 mm, and the second with an outside diameter of 4.5 mm and an inside diameter of 3.0 mm (the size used in current prototype engines). The 4.8 mm tubing included the following alloys: N-155, A-286, Incoloy 800, 19-9DL, CG-27, W-545, Inconel 718, Inconel 601, and HS-188. The 4.5 mm tubing included the following alloys: 12RN72, 253MA, Sanicro 31H, Sanicro 32, Inconel 625, Inconel 750, and Pyromet 901. Four of the tubing alloys were weld-drawn and the others were seamless tubing. The weld-drawn alloys were N-155, 19-9DL, Inconel 718(wd) and HS-188. A second lot of Inconel 718 (Inconel 718(a)) in the seamless version and an as-cold worked seamless version of the 12RN72(cw) were also tested.

Chemical analysis of the tube product as reported by the fabricator or determined at NASA LeRC are listed in table I. Ten of the alloys are iron-base superalloys with substantial amounts of chromium and nickel. The iron-base alloys are: N-155, A-286, Incoloy 800, 19-9DL, CG-27, W-545, 12RN72, 253MA, Sanicro 31H, and Sanicro 32. Five of the alloys are nickel base alloys, and include Inconel 601, Inconel 625, Inconel 718 , Inconel 750, and Pyromet 901. One alloy, HS-188, is cobalt-based. Average grain size of the heater tubes ranged from 7  $\mu m$  for HS-188, to 61  $\mu m$  for W-545 and are reported in table I. Prior to the endurance runs, several of the alloys were heat treated to increase their grain size and thus hopefully improve the elevated temperature creep-rupture properties. The alloy, heat treatment and grain size are as follows:

Alloy	Solution treatment	Atmosphere time	Cooling	Grain size, µM
N-155	1204° C	Vacuum 10 min	Fce.	17
A-286	1148° C	Vacuum 10 min	Fce.	54
Incoloy 800	1121° C	Vacuum 1 hr	Fce.	46
19 -9DL	1204° C	Vacuum 10 min	FceHe	25

The microstructure of the tubes before the endurance run are shown in figures 1(a) to (r). The limited supply of some tubes prevented obtaining microstructures of them before exposure to the endurance testing. The microstructure of these tubes were obtained from the cold end of the "hairpin" after endurance testing.

The tubing alloys were evaluated in the Stirling engine materials test rig in the form of a "hairpin" as shown in figure 2. Each leg of the "hairpin" was 30.5 cm long with 2.5 cm between legs. Four of these "hairpins" were attached in series to a copper header with internal passages and external tubes and valves for filling the four "hairpins." The copper header and attached tubes comprised a module. The module is shown in figure 3. The "hairpins" were attached to the copper header with gas-tight mechanical connectors. A pressure

transducer is located adjacent to the thermocouple plug at the top of the module. A thermocouple is also attached to the pressure transducer. When one tube failed during the test, the pressure in the remaining three tubes of that module was also lost. Before installation in the rig, each assembled module was leak checked to 10 MPa by pressurizing with helium and submersion in water. The modules were previously proof tested to 30 MPa by pressurizing with an organic solvent. Little difficulty was experienced in achieving leak proof modules.

Hydrogen doped with 1.0 vol % carbon dioxide ( $CO_2$ ) was used in both endurance tests. Analyses of the hydrogen used in the endurance run at 15 MPa are shown in table II. The hydrogen analyses for the endurance run at 21.6 MPa with CG-27 are also shown in table II. The modules were refilled every five hr during the initial 100 hr cycles of the endurance tests, due to the rapid permeation of hydrogen through the tube walls at 820° C. During the latter part of the endurance test, when the hydrogen permeation was substantially reduced, the modules were refilled with hydrogen once every week, which averaged 50 hr of testing. The modules pressurized with helium were repressurized only after "hairpin" replacement following a tube failure.

Analyses of the helium used in the test runs revealed no detectable amounts of oxygen.

# Stirling Engine Simulator Rig

The Stirling engine simulator rigs used in this program were designed and fabricated at the Lewis Research Center; they consist primarily of a combustion gas heating chamber and auxiliary heating, control and gas management systems. A schematic of the heating chamber is shown in figure 4. A detailed description of the rigs and their operation is given in reference 4.

An endurance run consisted of a series of 5-hr cycles to obtain the required exposure time of 3500 hr at 820° C. A typical heating cycle was made up of a 6 to 10 min preheat to get to the operating temperatures, a 5-hr hold at temperature, followed by a cool down to near room temperature. The cool down time between cycles in the furnace was 1 hr or longer. After cool down to about 25° C the modules containing hydrogen were vented, pressure transducers rezeroed and refilled. The modules containing helium did not require refilling after each cycle: they were evacuated and refilled only after "hairpin" replacement following a failure or leak. After completion of the test run or after failure, the "hairpins" were removed from the modules and sectioned for tensile testing and metallographic examination.

The modules were of the modified design to eliminate a "hot-zone" at the top of the "hairpin", approximately 23 cm from the bottom bend. This modification consisted of the installation of a 10.2 long sleeve (9.5 mm diam) around each tube leg in the "hot zone". This effectively reduced the temperature variation along each "hairpin" of each module.

The temperature inside the heating chamber of the rig was determined at the start of the first 3500 hr endurance run. The profile was determined by measuring the temperature at three locations on each module. The thermocouples were fastened to each module at the bottom bend of the "hairpin" as well as at

10.2 and 22.9 cm from the bottom bend. The temperature profile determined for the two endurance runs are shown in figures 5(a) and (b). This figure shows the temperature at the top, middle and bottom locations on the module plotted against module position around the furnace. Also shown are the tube alloys at the module location at the start of the run. Figure 5(a) shows the results for Rig A. The temperatures at the top varied from 770° to 870° C, with the highest temperature (870°C) at the location of the N-155 "hairpin" and the lowest temperature at the location of the Incoloy 800 "hairpin." The maximum temperatures at the middle and bottom locations were substantially lower than those of the maximum at the top location and varied from 800° to 843° C at the bottom locations and 780° to 830° C at the middle locations. Most tubing failures occurred in the top locations of the "hairpins." Figure 5(b) shows the temperature profile for Rig B, which is quite similar to that of Rig A. The temperatures at the top varied from 780° to 854° C with the highest temperature at the module containing Inconel 625. The temperatures at the middle location varied from 805° to 838° C. At the bottom location the temperatures varied from 813° to 851° C.

# Post Exposure Evaluations

Post exposure evaluation included tensile testing at room temperature and 820° C and metallography.

Tensile tests were conducted on tube specimens at room temperature and at 820° C. The tensile grips and a tensile specimen are shown in figure 6. The tensile specimens were 10.2 cm long when tested at room temperature and 17.8 cm long when tested at 820° C. A solid tool steel pin 2.5 cm long was inserted into the tube ends to prevent collapse of the tube during testing. The elongation after testing was determined from measurements of prescribed marks on the tensile specimens. All tests were conducted at a crosshead speed of 0.25 cm/min. Except where noted tests were conducted in duplicate.

Metallographic specimens were sectioned from the "hairpin" tubes taken from each module. The specimens were polished, appropriately etched and examined at magnifications of 100X and 500X.

# **RESULTS**

# Microstructure

As previously indicated the microstructure of the alloys before the endurance runs are shown in figures 1(a) to (r). The limited supply of some alloys prevented obtaining microstructures before endurance testing. The microstructures of these tubes 12RN72, 12RN72(cw), W-545, Inconel 601 and Inconel 625 were obtained from the cold end of room temperature tensile specimens after tensile testing. Note the dual grain size present in figure 1(n) for Inconel 718(wd). The small grain size area (10  $\mu$ m) is in the heat-affected weld zone and the larger grains (23  $\mu$ m) are in the base metal. This heat-affected weld zone was the location of the failures in the Inconel 718(wd) tubes and also in the other weld-drawn tube alloys. The microstructures of each tube from each alloy pressurized with hydrogen doped with 1.0 vol % CO2 and each alloy pressurized with helium after rig exposure are also shown in figures 1(a) to (r).

Minor changes in microstructure were found for most alloys which included growth and coalescence of the precipitate particles in the matrix and grain boundaries. There was, however, substantial grain growth in several tubes, CG-27, 12RN72, 12RN72(cw), Inconel 718(wd), and Inconel 718(a) (table III). The largest grain growth, from 36 to 113 um, was found in the CG-27 alloy for the tubes exposed to helium for 3500 hr as shown in figure 1(e). In general the alloys did not show major reaction to hydrogen doped with 1.0 vol % CO2 or the helium used to pressurize the tubes. The W-545 and 19-9DL were the only allovs showing any substantial reaction to the diesel fuel fire-side environment as can be noted in figures 1(f) and (d). Figure 1(f) for W-545 shows that the fire-side of the tube was oxidized to nearly one-fourth of the wall thickness. Figure 1(d) for 19-9DL shows the wall thickness was also severely reduced during the endurance test. This is similar to that found in the 1000-hr endurance run reported in reference 5, where 50 percent of the 19-9DL tube was lost, indicating that the fire-side burner environment has caused oxidation and spalling of the tubing outside surface. Incoloy 800, 12RN72 and 12RN72(cw) show a reduced wall thickness, after exposure, however these photomicrographs are from failed tubes where the wall thickness was severely reduced by bulging during failure. W-545 and Inconel 601, showed thinner and deformed surfaces in the unexposed condition, however, unexposed metallographic specimens were obtained from the grip end of failed tensile specimens.

# Hydrogen Permeability

The pressure of the gas contained in the modules, hydrogen doped with 1.0 vol %  $\rm CO_2$  or helium, was monitored during each of the 5-hr 820° C temperature cycles that made up the 3500 hr endurance run. The pressure in the modules that contained helium became constant after the module achieved the 820° C temperature and remained constant throughout the 5-hr cycle. However, the pressure in the modules that contained hydrogen doped with 1.0 vol %  $\rm CO_2$  varied from a maximum at the start of the 5-hr cycle to a low at the end of 5 hr at 820° C. The maximum pressure and the pressure at the end of the 5-hr cycle were used to calculate the hydrogen permeability coefficient,  $\phi$ , using the equation:

$$P = P_0^{1/2} - \frac{\phi A P_s Tt}{2LVT_s}$$

where

P pressure in closed system, MPa

Po original pressure, MPa

A permeated area, cm<sup>3</sup>

P<sub>S</sub> standard pressure, MPa

T temperature of system, K

t time, sec

- L membrane thickness, cm
- volume of system, cm<sup>3</sup>
- $T_s$  standard temperature, K

It should be noted that the Stirling materials simulator test rig, modules and tubes were not expressly designed for the measurement of permeation, but rather were designed for environmental endurance testing to determine the effects of burner and hydrogen environment on the life of tubes under pressure. Thus the permeation calculations should be considered as "apparent" permeation coefficients. Nonetheless, they are valuable in rating hydrogen (doped with 1.0 vol % CO<sub>2</sub>) permeation rates through the 16 alloys investigated.

# 3500 Hr Endurance Test of 16 Alloys at 15 MPa and 820° C

The results of the calculations of permeability coefficient,  $\varphi$  for selected 5-hr cycles of the endurance run at 15 MPa are shown in table IV. These data are shown plotted in figures 7, 8, and 9 for the iron, nickel, and cobalt base alloys, respectively. In general the hydrogen doped with 1.0 vol % CO2 resulted in lower hydrogen permeability coefficients, and thus lower hydrogen loss. All nickel-base alloys had hydrogen permeability coefficients less that 0.5x10^6 cm²/sec MPa¹/² after 110 hr into the 3500-hr endurance run and were all below 0.2x10^6 cm²/sec MPa¹/² at longer times during the 3500-hr endurance run. Only the three iron-base alloys, W-545, 19-9DL and 253MA, had hydrogen permeability coefficients above 2.5x10^6 cm²/sec MPa¹/² after 110 hr.

A ranking of the tested "hairpin" tubes according to their hydrogen permeability coefficient,  $\varphi$ , achieved after 250-hr exposure in the rig is given in table V. This time was chosen since it corresponds to the shortest failure time of any of the alloys tested and thus permits an equal comparison. Table V shows that the "hairpin" with the lowest hydrogen permeability coefficient is Pyromet 901 with a  $\varphi$  value of  $0.064 \times 10^{-6}$  cm²/sec MPa¹/². The next five alloys, CG-27, Inconel 601, Inconel 718(wd), Inconel 750 and 12RN72(cw) all had  $\varphi$  values below  $0.2 \times 10^{-6}$  cm²/sec MPa¹/². Note that the currently used N-155 alloy ranked number 10, i.e., nine "hairpin" tubes had lower hydrogen permeability coefficients. Only three "hairpin" tubes 253MA, W-545 and 19-90L had  $\varphi$  values above  $1.0 \times 10^{-6}$  cm²/sec MPa¹/² after 250-hr exposure in the rig, 2.47, 3.80 and  $5.05 \times 10^{-6}$  cm²/sec MPa¹/², respectively. Thus, using the desired goal of  $2.5 \times 10^{-6}$  cm²/sec MPa¹/² as the maximum hydrogen permeation coefficient that could be tolerated in a commercial highway vehicle, only two "hairpin" tubes, W-545 and 19-90L, failed to meet this criteria.

# 3500 Hr Endurance Test of CG-27 at 21 MPa and 820° C

The calculated hydrogen permeability coefficient,  $\phi$ , for selected 5-hr cycles of the endurance run at 21 MPa pressure, are shown in table VI. This shows the  $\phi$  value varied from  $3.10 \times 10^{-6}$  to  $0.08 \times 10^{-6}$  cm<sup>2</sup>/sec MPa<sup>1/2</sup> during the 500 hr. These data are shown plotted with the data obtained from the 3500-hr endurance run at 15 MPa (fig. 10). Note that the  $\phi$  values for the two endurance runs are similar to the  $\phi$  value from the run at 15 MPa falling within the scatter obtained from the five modules of the run at 21 MPa.

# Tubing Lives

Many of the "hairpin" tubes did not survive the 3500-hr endurance run at 15 MPa internal pressure. The tubes that contained helium had more failures than did those that contained hydrogen due to the higher constant pressure and hence stress maintained in the helium-containing tubes, throughout each of the 5-hr cycles at 820° C. In contrast, the hydrogen pressure generally decayed with time during each 5-hr cycle. The tube rupture lives for the 3500-hr endurance at 15 MPa pressure are shown in table VII. The tube rupture lives for the 3500-hr endurance run at 21 MPa using CG-27 are shown in table VIII.

3500 hr Endurance Run of 16 Alloys at 15 MPa and at 820° C.

The results of the 3500 hr Stirling engine simulator test rig endurance run at 15 MPa and 820° C are given in table VII. After 3500 hr. no failures were noted in the "hairpin" tubes of CG-27 and Pyromet 901, regardless of the gas, either helium or doped hydrogen. Two other tubes, 12RN72 and Inconel 625 which had rupture lives in excess of 3500 hr for those which contained hydrogen, however, they did have failures in the tubes which contained helium after 1598 and 2856 hr, respectively. There were no failures in the Incoloy 800, Sanicro 31H, Inconel 601, 253MA and Sanicro 32 "hairpin" tubes that contained doped hydrogen, however, these were removed after 130, 165, 590, 2099 and 2919 hr, respectively, due to their limited lives when pressurized with helium. Note that for W-545, 12RN72(cw), and Inconel 750 the rupture lives in the "hairpin" tubes which contained hydrogen are less than those that contained helium, indicating that there may be possible hydrogen environment degradation or embrittlement. However, the results of the tensile tests did not substan-It is noted that the Inconel 718(wd) and Inconel 718(a) "hairpin" had significantly different rupture lives, 514 and 1672 hr. respectively. As there is no significant difference in composition between the two tubes, the three-fold improvement in performance of the Inconel 718(a) is attributed to its being a seamless tube rather than weld-drawn as was the Inconel 718(wd).

A ranking of the 16 alloys according to the average rupture lives of the tubes that contained helium is given in table IX and shown plotted in figure 11. The two alloys CG-27 and Pyromet 901 both had rupture lives in excess of 3500 hr in either the helium containing tubes or the doped hydrogen containing tubes. The alloy with the shortest rupture life was Incoloy 800. The "hairpin" tubes pressurized with helium failed by creep-rupture in 118 hr. Note that there are eleven "hairpin" tubes ranked higher than N-155 (606 hr rupture), the alloy currently used an heater head tubes in prototype highway vehicles. CG-27, Pyromet 901, Inconel 625, W-545, Inconel 718(a), 12RN72, HS-188, 12RN72(cw), 253MA, Sanicro 32 and Inconel 750 all had rupture lives greater than 700 hr. The remaining tubes ranked lower than N-155. In descending order they are 19-9DL, Inconel 601, Inconel 718(wd), A-286, Sanicro 31H and Incoloy 800.

# 3500 hr Endurance test of CG-27 at 21 MPa and 820° C

The results of the 3500-hr endurance run at 21 MPa pressure for the CG-27 alloy are shown in table VIII. Ten modules were tested, five with hydrogen and five with helium. No creep-rupture failures occurred in either the doped

hydrogen or helium pressurized "hairpin" when tested at 820° C. Three failures did occur, but these are attributed to high temperatures caused by a defective heat-shield and a 270° C over-temperature spike. The defective heat-shield can be seen on the module on the right side of figure 12. It has essentially eroded away during the endurance run. This loss of the heat-shield resulted in a temperature estimated to be 40° to 60° C higher than in modules with intact heat-shields. The failures in the tubes of modules 6 and 10 occurred immediately after an over-temperature malfunction in the rig at 1075 hr into the 3500-hr endurance run. During the over-temperature spike the modules were in excess of 1090° C for 6 to 10 min. No failures occurred in the remaining seven modules which ran for the full 3500 hr at 820° C and 21 MPa pressure.

# Tensile Properties

Tensile properties of the unexposed tubing were determined where material availability permitted. The endurance tested, exposed, "hairpin" tubes of all alloys were sectioned for tensile testing to determine the effect of rig environment on the tensile properties. Each of the alloys had been exposed to hydrogen doped with 1.0 vol %  $\rm CO_2$ , helium and the burner combustions products. Both room temperature and high temperature (820° C) tensile tests were conducted. The results of these tests for the two 3500-hr endurance runs are described in the following sections.

# TENSILE PROPERTIES OF 15 MPa TESTED ALLOYS

# Room Temperature

The room temperature tensile properties of the tubing alloys both prior to the endurance runs as well as after are presented in table X and for the 3500-hr endurance run with 16 alloys at 15 MP, and shown graphically in figure 13.

The room temperature tensile properties of the 16 alloys, prior to use in the endurance test at 15 MPa pressure are given in table X. The ultimate strengths ranged from a low of 552 MPa for Incoloy 800 to a high of 1364 MPa for CG-27. The tensile elongation for alloys were good and ranged from 14.5 percent for the high strength CG-27 to 60.3 percent for 19-9DL. Hydrogen exposure in the rig resulted in significant losses in ultimate strength for six of the "hairpin" tubes, W-545, 19-9DL, Inconel 718(a), Inconel 750, Pyromet 901, and Sanicro 32, CG-27. The greatest loss in strength occurred in the W-545 tubing, where the ultimate tensile strength was reduced from 988 MPa for the unexposed material to 254 MPa. The ultimate strength of the Inconel 750 dropped from 1197 to 553 MPa, Pyromet 901 dropped from 1221 to 591 MPa, and Sanicro 32 dropped from 598 to 347 MPa. The ultimate strength of CG-27 dropped from 1364 to 736 MPa and 19-9DL dropped from 767 to 420 MPa. Losses in ductility ranged from 38 percent for CG-27 exposed to hydrogen to 95 percent loss in ductility for Sanicro 32 exposed to hydrogen. Exposure in the rig resulted in little or no loss in ultimate strength at room temperature in four of the "hairpin" tubes: N-155, A-286, Inconel 601, and 253MA. There were, however, large losses in ductility in three of the four alloys, a 24 percent loss for N-155, 70 percent loss for A-286 and a 65 percent loss for 253MA. These losses were similar for the tubes that contained helium or hydrogen, indicating an

aging effect. The ductility of the Inconel 601 improved slightly, from 40 to 45 percent. Doped hydrogen exposure in the rig resulted in a gain in ultimate tensile strength for two of the "hairpin" tubes, HS-188, Inconel 718(wd), Helium exposures showed similar gains in three "hairpin" tubes, Inconel 625, Incoloy 800 and Sanicro 32. Generally, the gains in strength were not large, however, the Inconel 718(wd) with helium improved from 875 to 956 MPa. The changes in ductility for these five "hairpin" tubes ranged from a loss of 23 percent for Incoloy 800 (in helium) to a loss of 95 percent for Sanicro 32 (in doped hydrogen).

The 820° C tensile properties of the tubing alloys both prior to the endurance runs as well as after are presented in table XI and are shown graphically in figure 14. The elevated temperature strength at 820° C ranged from 138 MPa for Sanicro 31H to 540 MPa for Inconel 718(a). The tensile elongation at 820° C ranged from 14 percent for CG-27 to 70.2 percent for Sanicro 31H.

Exposure in the rig at 15 MPa at 820° C resulted in large losses in ultimate strength for seven of the 18 "hairpin" tubes. The greatest losses in strength occurred in: W-545, -64 percent; Inconel 718(a), -45 percent; Pyromet 901, -43 percent; Inconel 718(wd), -35 percent; Inconel 750, -35 percent; CG-27, -32 percent; and 19-90L, -30 percent. There were minor losses in strength in seven other "hairpin" tubes: N-155, A-286, Incoloy 800, 253MA, Sanicro 32, Inconel 601, and HS-188. There were slight gains in strength in two: Inconel 625, and Sanicro 31H. The absolute strength of the alloys after exposure in the rig is of importance in ranking the alloys. The "hairpin" tubes with the highest ultimate strength after rig exposure to hydrogen were CG-27 (378 MPa), Inconel 625 (342 MPa), HS-188 (342 MPa), Inconel 718(wd) (339 MPa), Inconel 718(a) (318 MPa) and Pyromet 901 (300 MPa).

There were large losses in ductility after rig exposure in four of the "hairpin" tubes: W-545, -77 percent; 19-9DL, -53 percent; Pyromet 901, -50 percent and Sanicro 31H, -28 percent. As noted previously, there were also large losses in ultimate strength in three of these four W-545, 19-9DL, and Pyromet 901. In six of the "hairpin" tubes there were gains in ductility after rig exposure. This occurred in CG-27, +207 percent; Inconel 718(wd), +205 percent; Inconel 718(a), +148 percent; N-155, +137 percent; Inconel 750, +83 percent; and A-286, +72 percent. Generally this gain in ductility at 820° C was accompanied by a decrease in ultimate tensile strength at 820° C.

## TENSILE PROPERTIES OF 21 MPa TESTED CG-27

The tensile data for CG-27 prior to and after rig exposure at 21 MPa for 3500 hr at 820° C are given in table XII and are shown graphically in figure 15. The room temperature (25° C) ultimate tensile strength was 1364 MPa and the tensile elongation was 14.5 percent. The elevated temperature tensile strength (820°) was 529 MPa and the tensile elongation was 14 percent. Note that both the doped hydrogen and helium containing tubes were degraded about the same amount when tested at room temperature or 820° C, indicating an aging effect rather than an environment effect. The helium tube loss 544 MPa (40 percent) and the doped hydrogen tube loss 577 MPa (42 percent).

### DISCUSSION

The results of the 3500-hr endurance run at 15 MPa pressure show that eleven of the "hairpin" tubes studied had longer lives than did the currently used N-155 (606 hr). The temperature distribution in the rigs may account for some of the alloys being stronger than N-155 since N-155 was at the highest temperature in Rig A. Two alloys, CG-27 and Pyromet 901 had no failures in 3500 hr and two other alloys Inconel 625 and W-545 had lives of 2856 and 2777 hr, respectively. The failure times for the modules of a given alloy that contained hydrogen were generally longer than those that contained helium. This is due to the constant higher pressure maintained in the helium modules. The results for Inconel 750, W-545, 12RN72(cw) and 19-9DL show that the "hairpin" tubes that contained hydrogen had earlier failures than did the tubes that contained helium. These "hairpin" tubes also had larger tensile property degradation in the modules that contained hydrogen (table XIII). These results are indications of possible hydrogen embrittlement in these materials.

Comparison of the failure times of the Inconel 718(wd) and Inconel 718(a) as shown in table VII shows that the Inconel 718(a) had substantially longer life in both hydrogen filled and helium filled tubes. The significant difference between the two tubes is the methods of fabrication, Inconel 718(wd) being weld-drawn and Inconel 718(a) being seamless. The absence of a weld fusion line in the Inconel 718(a) eliminates a high temperature fracture prone zone and thus extends the life at 820° C. The failure time improved from 514 hr for Inconel 718(wd) helium filled tubes to 1672 hr for the helium filled Inconel 718(a) seamless tubes.

The results of the two 3500-hr endurance runs again show that hydrogen permeates through the hot tube walls and must be replenished periodically. whereas helium is readily contained in the "hairpin" tubes for each 5-hr cycle at temperature of 820° C and pressures of 15 and 21.6 MPa. The rate of hydrogen permeation was found to be substantially educed in most alloys with the use of 1.0 vol % carbon dioxide as a dopant in the hydrogen. The rate of hydrogen permeation was found not to be constant but rather is variable and is influenced by alloy composition and  $0_2/C0_2$  content of the hydrogen used. The reduction of hydrogen permeability during the endurance test is thought to be associated with the formation of a very thin oxide film on the inside surface of the tube. The external oxide on most alloys studied was tightly adherent, however, in the 19-9DL tubes the external fire-side oxide spalled severely, thus reducing the tube wall thickness. This behavior was also found in the endurance runs previously conducted at 820° and 860° C (described in ref. 5). As would be expected 19-9DL had the highest apparent hydrogen permeability of all alloys. This is shown plotted in figure 16. In general the nickel-base alloy tubes had lower hydrogen permeability coefficients than the iron-base alloy tubes or the cobalt-base alloy tube. However, the CG-27. 12RN72 and 12RN72(cw) tubes had low hydrogen permeation coefficients,  $0.13 \times 10^{-6}$ ,  $0.18 \times 10^{-6}$ , and  $0.31 \times 10^{-6}$  cm<sup>2</sup>/sec MPa<sup>1/2</sup>, respectively after 250 hr. Examination of figure 16 shows that only three "hairpin" tubes, 253MA, W-545, and 19-9DL had hydrogen permeability coefficients above  $1.0 \times 10^{-6}$  cm<sup>2</sup>/sec MPa<sup>1/2</sup>. Thus it can be concluded that the 1.0 vol % carbon dioxide as a dopant in the hydrogen was effective in reducing the rate of hydrogen permeation while at 820°C. In view of the very low permeability coefficients obtain using hydrogen doped with 1.0 vol % CO2 the possibility exists that a reduced dopant level, below 1.0 vol %, may be suitable for use in a commercial vehicle. Also.

it appears that the goal of a hydrogen permeability coefficient in the order of  $2.5 \times 10^{-6}$  cm<sup>2</sup>/sec MPa<sup>1/2</sup> for commercial vehicles can readily be achieved with most of the alloys studied.

### SUMMARY OF RESULTS

Endurance testing of sixteen tubing alloys in a diesel-fuel-fired Stirling engine simulator materials test rig for 3500 hr at 820° C while pressurized with either hydrogen doped with 1.0 vol %  $\rm CO_2$  or helium had the following results:

- (1) The CG-27 and Pyromet 901 tubes did not fail during the 3500 hr endurance run at the 15 MPa pressure. The remaining 16 tubes, pressurized with helium failed by creep-rupture.
- (2) No creep-rupture failures occurred in the CG-27 tubes when endurance test at 21.6 MPa.
- (3) The 1.0 vol % CO<sub>2</sub> as a dopant in hydrogen was effective in reducing hydrogen permeation at 820 $^{\circ}$  C.
- (4) Most alloys lost hydrogen rapidly during the early 5-hr segment of the endurance test, however, only three alloys, iron-based 19-9DL, W-545, and 253MA had hydrogen permeability coefficients,  $\phi$ , above 1.0x10<sup>-6</sup> cm<sup>2</sup>/sec MPa<sup>1/2</sup> at the end of the test.
- (5) The permeability coefficients,  $\phi$ , of the nickel-base alloys were in general, lower than those of the iron-base or cobalt-base alloys. However, three iron-based tubes CG-27, 12RN72, and 12RN72(cw) had  $\phi$  values below  $0.06 \times 10^{-6}$  cm<sup>2</sup>/sec MPa<sup>1/2</sup>, lower than the nickel-base alloys.
- (6) Tensile tests conducted on the rig exposed tubes showed that the CG-27 alloy has identical room temperature ultimate strength as the N-155 alloy and the 820° ultimate strength of CG-27, 360 MPa, is 100 MPa greater than the N-155.

#### REFERENCES

- 1. Brogan, J. J.: Highway Vehicle Systems Program Overview. Highway Vehicle Systems. CONF-771037, 1978, pp. 3-5.
- 2. Stephens, Joseph R., et al.: Materials Technology Assessment for Stirling Engines. NASA TM-73789, 1977.
- 3. Ragsdale, Robert G.: Stirling Engine Project Status. Proceedings of Highway Vehicle Systems. CONF-781050, 1979, pp. 287-291.
- 4. Misencik, John A.: Evaluation of Candidate Stirling Engine Heater Tube Alloys for 1000 Hours at 760° C. DOE/NASA/1040-18, NASA TM-81578, 1980.
- 5. Misencik, John A.: Evaluation of Candidate Stirling Engine Heater Tube Alloys at 820° and 860° C, DOE/NASA 51040-39, NASA TM-82837, 1982.

- 6. Misencik, John A.: Evaluation of Dopants in Hydrogen to Reduce Hydrogen Permeation in Candidate Stirling Engine Heater Head Tube Alloys at 760° and 820° C, DOE/NASA 51040-41. NASA TM-82920, 1982.
- 7. Misencik, John A.: Evaluation of  ${\rm CO_2}$  and  ${\rm CO}$  Dopants in Hydrogen to Reduce Hydrogen Permeation in the Stirling Engine Heater Head Tube Alloy, CG-27. NASA TM-83535, 1983.

TABLE I. - COMPOSITION, METHOD OF FABRICATION, GRAIN SIZE, AND TUBE SIZE FOR TUBING ALLOYS

HS-188	Weld- drawn		7	4.8		22 23.1 8a1 .67 .13.9 .38 .11.
Pyromet 901	Seamless		46	4.3		12.33 Ba1 .10 5.90 2.60 .19 .028
Inconel 750	Seamless		32	4.3		15.6 8a1 .16 .2.50 .2.50 .23 .72 .046 .07
Inccnel 718(a)	Seamless		14	4.8		18.05 8a1 .23 .23 2.93 1.03 b5.00 .11 .52 .04 .06
Inconel 718(wd)	Weld- drawn		a(7)23	4.8		17.7 Ba1 .03 .05 3.02 3.02 1.12 b5.18 .56 .56
Inconel 625	Seamless		16	4.3		21.0 8a1 09 8.04 34 3.15 33 33 02
Inconel 601	Seamless		33	4.8		23.68 Bal .14 .152 .04 .05 .05
Sanicro 32	Seamless		19	4.3		21.5 31.9 65 05 07 03
Sanicro 31H	Seamless		Ξ	4.3	ion, wt %	21.2 31.7 .65 .05 .05 .07 .07
253MA	Seamless		21	4.3	Composition, wt	20.96 11.5 1.50 1.52 2.05 1.82 .088 .20 2.001
472	N.	Seamless	6	4.3		24.36 1.90 1.62 .009 .010 .015
12RN72	ъ	Seam	10	4.3		24.05 1.90 1.50 1.50 1.50 1.50 0.01 0.01 0.01 0.0
W-545	Seamless		19	4.8		27.7 1.32 1.7 2.8 .49 .15 .026 .026
CG-27	Seamless		36	4.8		13.0 37.8 <.05 5.57 2.3 .97 (.1 1.66 .004
19-9DL	Weld- drawn		25	4.8		18.3 8.76 1.02 1.18 1.18 0.37 29
Incoloy 800	Seamless		46	4.8		22.5 32.6 73 52 53 54 01
A-286	Seamless	•	54	4.8		24.7 1.01 1.17 2.12 .62 .06 .32 .32
N-155	Weld- drawn		17	4.8		21.2 19.9 19.0 19.0 1.45 3.03 3.03 1.05 1.05 1.10 1.05
Alloy	Fabri- cation		Grain size, µm	Tube size,	Element	Chromium Nickel Cobalt Manganese Molydenum Titanium Columbium Silicon Nitrogen Carbon Nitrogen Copper Vanadium Boron Lanthanum

aweld zone. bcb/Ta.

TABLE II. - HYDROGEN ANALYSIS OF HYDROGEN USED IN THE TWO ENDURANCE RUNS

Test time,	Bottle number			Analysi	s, vol %	,			
""	Trumber	CO <sub>2</sub>	02	N <sub>2</sub>	А	He	CO	CH <sub>4</sub>	
Rig A - 15 MPa									
0 - 387 387 - 720 720 - 1088 1088 - 1546 1546 - 2060 2060 - 2550 2550 - 2705 2705 - 3324 3324 - 3500	727506 618258 680925 573098 486222 277027 685865 467562 124519	1.05 1.10 .98 1.11 .98 .99	0.002 .002 .0000	0.075 .086 .0000	0.018 .018 .0000	0.0000	0.0000	0.0217	
Rig B - 15 MPa									
0 - 525 525 - 1222 1222 - 1938 1938 - 2743 2743 - 3180 3180 - 3340 3340 - 3500	727519 377374 643981 376849 449089 577823 478101	1.08 1.12 1.02 .91 .91	.003	.095 .0000 .017	.20 .0000	.0000	.0000	0.0178	
Rig A (CG-27 at 21 MPa)					-				
0 - 1045 1045 - 2785 2785 - 3500	12459 67634 112878	.90 1.04 1.04	same lo	t as 467	562				

TABLE III. - GRAIN SIZE OF "HAIRPIN" TUBES
BEFORE AND AFTER RIG EXPOSURE

Material	Unexposed grain size,		Rig e	xposed	· · · · · · · · · · · · · · · · · · ·
	yrain size, µm		н <sub>2</sub>		Не
		Grain size, µm	Exposure time, hr	Grain size, µm	Exposure time, hr
N-155 A-286 Incoloy 800 19-9DL CG-27 W-545 12RN72 12RN72(cw) 253MA Sanicro 31H Sanicro 32 Inconel 601 Inconel 625	17 54 46 25 36 61 10 9 21 11 19 33	17 51 47 26 107 64 15 11 21 11 22 38	<sup>a</sup> 1725 435 130 450 2624 3500 1068 1436 2099 165 2919 3500	16 555 444 25 113 69 16 18 21 13 21 34	a743 435 409 450 3500 2895 1272 1948 1863 163 1007 555
Inconel 718(wd) Inconel 718(a) Inconel 750 Pyromet 901 HS-188	23 14 32 46 7	28 16 33 54 10	565 1990 1494 3500 2326	27 17 31 52	555 1450 905 3500 1463

 $<sup>^{\</sup>rm a}{\rm Exposure}$  time in rig; hours at 820° C.

TABLE IV. - APPARENT HYDROGEN PERMEABILITY COEFFICIENT 🔹 AS A FUNCTION OF RIG EXPOSURE TIME

			ω ω		-			_	_	<u> </u>			р				
			HS-188	15.39	4.97	2.17	1.30	1.17	Š.	08. 69.	.37	.26	Failed	<u>4</u> <del>0</del>			
			Pyromet 901	1.03	61.	.12	60.	80.	۶n <b>.</b>	.09	.63	.064	.18	.30	.13	.14	.058
			Incone 1 750	0.31	.28	91.		77.	.20	.18	Failed	187					
į.			Inconel 718(a)	0.42	.25	12.	.27	81.	<u>.</u>	.23	.20		.21	Failed	1 791		
	2		Inconel 718(wd)	0.49	.21	.20		7.		.15	.36	Failed	253				
	cm <sup>2</sup> /sec MPa <sup>1</sup> /2		Inconel 625	0.68	.55	.48	> %		.34	.33	.31	.26	.29	•28	.30	.22	•33
	10-6 cm <sup>2</sup> /		Inconel 601	0.46	.42	.22	13	.16	<u>.</u>	.20	.16	Removed					
		terial	Sanicro 32	6.86	1.96 1.40	1.43	30.	36.	.93	.85	.57	09.	.56	.26	.31	Removed	6067
	y coeffic	Hairpin tube materia	Sanicro 31H	8.74	3.17	1.50	.73	88.	-	.99 Removed	501						
	rmeabilit	Hairpi	253MA	6.56	4.22	2.95	2.49	, ,	60.7	2.47	1.79	1.89	1.41	1.31	Removed	6603	
	ed ue		(cw)	7.59	60.	.42	96	2	.28		.13	.15	Failed	- 30			
	60,		12R (c		• •								ш.				
	ent Hydrog		12RN72 12R			.85	70	·	.55	.31	.26	=	.19 F	.095	90.	.085	.10
	Apparent Hydrogen permeability coefficient, *,		-	7		7.52 1.35 6.78 .85		5.38		3.80 .31	3.99 .26					• 085	.10
	Apparent Hydrog		12RN72	10.70 7	9.24 1.72	7.52	6.34	5.38				F.	.19	.095		.062	.14
	Apparent Hydrog		W-545 12RN72 1	12.43 10.70 7	9.24 1.72	7.52	19 6.34	5.38	.20	3.80	3.99	2.63 .11	91. 2.15 90.	Failed .095			
	Apparent Hydrog		90L CG-27 W-545 12RN72 1	47 1.63 12.43 10.70 7 1.05 1.05 4.81	8.98 .45 9.24 1.72	7.52	19 6.34	3.67 5.38	.20	51 5.39 05 .13 3.80	5.99 .14 3.99	Failed .098 2.63 .11	91. 2.15 90.	Failed .095			
	Apparent Hydrog		19-9DL CG-27 W-545 12RN72 1	13.47 1.63 12.43 10.70 7	.88 8.98 .45 9.24 1.72	.71 4.62 .21 6.78	73 4.2 6.34	3.67 5.38	.20	3.51 5.39 5.05 .13 3.80	5.99 .14 3.99	Failed .098 2.63 .11	91. 2.15 90.	Failed .095			
	Apparent Hydrog		Incoloy 19-9DL CG-27 W-545 12RN72 1	1.57 13.47 1.63 12.43 10.70 7 1.28 1.28 1.39 7 4.81	.88 8.98 .45 9.24 1.72	.71 4.62 .21 6.78	1.13 73 4.2 6.34	3.67 5.38	.93 .76 5.20	3.51 5.39 Removed 5.05 .13 3.80	5.99 .14 3.99	Failed .098 2.63 .11	91. 21.5 90.	Failed .095			
	Rig Apparent Hydrogi	posure time.	N-155 A-286 Incoloy 19-9DL CG-27 W-545 12RN72 1	12.93 1.57 13.47 1.63 12.43 10.70 7 6.10 1.28 10.78 1.05	6.34 2.93 .88 8.98 .45 9.24 1.72	1.85 2.0 .81 5.48 .25 7.52 1.41 1.32 .71 4.62 .21 6.78	1.09 1.13 73 4.2 6.34	3.67 5.38	.93 .76 .20	.37 .57 Removed 5.05 .13 3.80	Failed 5.99 .14 3.99	Failed .098 2.63 .11	91. 21.5 90.	Failed .095			

TABLE V. - RANKING OF TUBES AS TO APPARENT HYDROGEN PERMEABILITY COEFFICIENT

Rank	Tube	φ after 250 h	r
1	Pyromet 901	0.064	
2	CG-27	.13	
3	Inconel 601	.15	
4	Inconel 718(wd)	.15	
5	Inconel 750	.18	
6	12RN72(cw)	.18	
2 3 4 5 6 7 8 9	Inconel 718(a)	.23	
8	12RN72	.31	
9	Inconel 625	.33	
10	N-155	.37	
11	A-286	.57	
12	HS-188	.69	
13	Incoloy 800	a.76	
14	Sanicro 32	85	
15	Sanicro 31H	b,99	
16	253MA	2.47	
17	W-545	3.80	
18	19-9DL	5.05	

<sup>a</sup>After 100 hr - failed at 130 hr. <sup>b</sup>After 100 hr - failed at 165 hr.

TABLE VI. - APPARENT HYDROGEN
PERMEABILITY COEFFICIENT
- 

FOR CG-27 TESTED AT
21 MPa and 820° C

re $\phi$ , $10^{-6}$ , cm <sup>2</sup> /sec MPa <sup>1/2</sup>						
	Module					
1	3	5	7	9		
3.10 1.05 .71 .39	2.65 1.06 .40 .26	2.52 1.09 .18 .39	1.46 .66 .32 .22	1.36 .70 .41 .28		
	1 3.10 1.05 .71 .39	1 3 3.10 2.65 1.05 1.06 .71 .40 .39 .26 .31 .25	Module  1 3 5  3.10 2.65 2.52 1.05 1.06 1.09 .71 .40 .18 .39 .26 .39 .31 .25 .27	Module           1         3         5         7           3.10         2.65         2.52         1.46           1.05         1.06         1.09         .66           .71         .40         .18         .32           .39         .26         .39         .22           .31         .25         .27         .16		

 $^{\rm a}{\rm After}~500~{\rm hr}$  pressures monitored but not recorded.

TABLE VII. - RUPTURE LIVES FOR "HAIRPIN" TUBES ENDURANCE TESTED AT 15 MPa AND 820° C FOR 3500 hr

Alloy	Environment	Rupture life, hr	Average hr
N-155	He	535, 571, 576, 743	606
	H <sub>2</sub>	778, 955, 1209, 1535, 1725	1240
A-286	He	339, 424, 435	399
	H <sub>2</sub>	400, 422, 435	419
Incoloy 800	He	106, 130	118
	H <sub>2</sub>	No failures (removed - 130 hr)	a130
19-9DL	He	610, 640, 685, 707	601
	H <sub>2</sub>	525, 555, 605, 720	601
CG-27	He	None in 3500 hr	<sup>a</sup> 3500
	H <sub>2</sub>	None in 3500 hr	<sup>a</sup> 3500
W-545	He	2295, 2864, 2974, 2974	2777
	H <sub>2</sub>	1911, 2834	2372
12RN72	He	1262, 1412, 1652, 1677, 1978	1598
	H <sub>2</sub>	None in 3500 hr	<sup>a</sup> 3500
12RN72(cw)	He	1087, 1172, 1912	1374
	H <sub>2</sub>	1021, 1097, 1245, 1436	1200
253MA	He	1016, 1053, 1148, 1863	1273
	H <sub>2</sub>	None in 2099 hr	<sup>a</sup> 2099
Sanicro 31H	He	145, 163, 165	154
	H <sub>2</sub>	None in 165 hr	a 165
Sanicro 32	He	680, 695, 950, 1007	878
	H <sub>2</sub>	None in 2919 br	<sup>a</sup> 2919
Inconel 601	He	545, 566, 59 <sup>r</sup>	567
	H <sub>2</sub>	None in 590 nr	a <sub>590</sub>
Inconel 625	He	2603, 3110	2856
	H2	None in 3500 hr	<sup>a</sup> 3500
Inconel 718(wd)	He	475, 495, 522, 536, 545	514
	H <sub>2</sub>	525, 1005	765
Inconel 718(a)	He	1208, 1480, 1496, 1505	1672
	H <sub>2</sub>	1821, 1990, 2040, 2040	1925
Inconel 750	He	640, 850, 899	796
	H <sub>2</sub>	281, 715, 715	570
Pyromet 901	He	None in 3500 hr	<sup>a</sup> 3500
	H <sub>2</sub>	None in 3500 hr	<sup>a</sup> 3500
HS-188	He	1252, 1410, 1445, 1463	1392
	H <sub>2</sub>	1415, 1486, 1916, 2326	1785

<sup>&</sup>lt;sup>a</sup>Module removed from test rig unruptured.

TABLE VIII. - RUPTURE LIVES FOR CG-27 ENDURANCE TESTED FOR 3500 hr, AT 21 MPa AND 820° C

Module number	Rupture life, hr	Average time, hr
Rig Ba		
<sup>C</sup> 1 6 8 9	2624, 3393 1075, 1100, 1115 None None	3008 1097
10 Rig A	1075	1075
1 2 3 4 5 66 (6) c <sub>7</sub> (1) 8 (8) 9 (9) d <sub>10</sub> (10)	None None None None 1075, 1100, 1115 2624, 3393 None None	b3500 b3500 b3500 b3500 b3500 1097 3008 b3500 b3500 b3500

aTransferred to Rig A after 1570 hr. bNo creep-rupture failures. CHeat shield failed while in Rig A. dFailure due to 270° C over temperature spike.

TABLE IX. - RANKING OF TUBES BY RUPTURE LIVES IN 15 MPa HELIUM AT 820° C

Rank	Alloy	Average rupture life in helium tubes, hr
a <sub>1</sub>	CG-27 Pyromet 901	3500 3500
3	Inconel 625 W-545	2856 2777
a2 3 4 5 6 7 8	Inconel 718(a) 12RN72	1672 1598
8	HS-188 12RN72(cw)	1392 1374
9 10	253MA Sanicro 32	1273 878
11 12 13	Inconel 750 N-155 19-9DL	796 606 601
14	Inconel 601 Inconel 718(wd)	567 514
16	A-286 Sanicro 31H	399
18	Incoloy 800	154 118

<sup>&</sup>lt;sup>a</sup>No creep-rupture failures, ranked alphabetically.

TABLE X. - ROOM TEMPERATURE TENSILE PROPERTIES OF TUBING BEFORE AND AFTER ENDURANCE TESTING AT 820° C IN EITHER 15 MPa  $\rm H_2$  + 1% CO $_2$  or He

Alloy	Rig environment	Rig exposure time, hr	0.2 percent offset yield strength, MPa	Ultimate tensile strength, MPa	Elongation, percent
N-155	Unexposed Helium Hydrogen	743 1725	480 285 337	878 785 761	45 34 
A-286	Unexposed Helium Hydrogen	435 422	212 225 214	635 508 476	45.7 13.5 10
Incoloy 800	Unexposed Helium Hydrogen	130 130	181 225 199	552 570 551	39 30 35
19-9DL	Unexposed Helium Hydrogen	483 605	290 312 357	767 524 420	60.3
CG-27	Unexposed Helium Hydrogen	3500 3500	899 597 474	1364 757 736	14.5 8 9
W-545	Unexposed Helium Hydrogen	2974 3500	508 370 149	988 <sup>5</sup> 540 254	32 8 3
12RN72 <sup>C</sup>	Unexposed Helium Hydrogen	1948 3500	291 275	586 518	44 25
12RN72(cw) <sup>C</sup>	Unexposed Helium Hydrogen	2826 1912	357 295	611 558	b <sub>26</sub>
253MA	Unexposed Helium Hydrogen	1863 2099	330 355 3 i	731 615 692	57 20 24
Sanicro 31H	Unexposed Helium Hydrogen	163 165	92 235 239	560 557 576	42 25 42
Sanicro 32	Unexposed Helium Hydrogen	680 2919	290 283 248	598 553 347	42.8
Inconel 601	Unexposed Helium Hydrogen <sup>b</sup>	555 590	291 233 241	665 536 585	40 42 45
Inconel 625	Unexposed Helium Hydrogen	2856 3500	433 523 515	874 904 848	53 31

<sup>&</sup>lt;sup>a</sup>Average of two tests except where noted. <sup>b</sup>Single test. <sup>C</sup>Lack of sufficient material precluded unexposed tensile testing.

TABLE X. - CONCLUDED.

Alloy	Rig environment	Rig exposure time, hr	0.2 percent offset yield strength, MPa	Ultimate tensile strength, MPa	Elongation, percent
Inconel 718(wd)	Unexposed Helium Hydrogen	495 565	404 610 558	875 956 894	41.5 29 25.6
Inconel 718(a)	Unexposed Helium Hydrogen	1480 2100	543 394 475	984 792 721	44.5 22
Inconel 750	Unexposed Helium Hydrogen	1060 1495	722 333 355	1197 838 553	23
Pyromet 901	Unexposed Helium Hydrogen	3500 3500	842 729 350	1221 1095 591	22.5 6 5
HS-188	Unexposed Helium Hydrogen	1463 2326	404 584 574	875 985 928	41.5

<sup>&</sup>lt;sup>a</sup>Average of two tests except where noted.
<sup>b</sup>Single test.
<sup>c</sup>Lack of sufficient material precluded unexposed tensile testing.

TABLE XI. - TENSILE PROPERTIES AT 820° C<sup>a</sup> OF TUBING ALLOYS BEFORE AND AFTER ENDURANCE TESTING AT 820° C IN EITHER 15 MPa H<sub>2</sub> + 1% CO<sub>2</sub> or He

Alloy	Rig environment	Rig exposure time, hr	0.2 percent offset yield strength, MPa	Ultimate tensile strength, MPa	Elongation percent
N-155	Unexposed Helium Hydrogen	743 1725	244 163 178	296 249 258	b24.5 57.5 50
A-286	Unexposed Helium Hydrogen	435 435	157 145 127	199 176 174	29 50 44
Incoloy 800	Unexposed Helium Hydrogen	130 130	91 121 108	162 161 152	62 53 52
19-9DL	Unexposed Helium Hydrogen	483 605	147 115 154	230 159 183	37.5 16 10
CG-27	Unexposed Helium Hydrogen	3500 3500	363 275 233	529 378 356	14 43.5 30.5
W-545	Unexposed Helium Hydrogen	2974 3500	398 128 142	417 147 158	20  4.5
12RN72 <sup>C</sup>	Unexposed Helium Hydrogen	1948 3500	196 121	226 167	58
12RN72(cw) <sup>C</sup>	Unexposed Helium Hydrogen	2826 1912	300 24	178 163	54 56
253MA	Unexposed Helium Hydrogen	1863 2099	137 140 110	190 157 171	44.8 36 52
Sanicro 31H	Unexposed Helium Hydrogen	163 165	122  123	138 136 152	70.2 55 50
Sanicro 32	Unexposed Helium Hydrogen	695 2919	137 127 114	148 139 137	34
Inconel 601	Unexposed Helium Hydrogen <sup>b</sup>	555 590	149 154 148	175 177 170	52.5 46 45
Inconel 625	Unexposed Helium Hydrogen	2856 3500	225 258 272	309 348 342	43 47

aAverage of two tests except where noted.

bSingle test.

CLack of sufficient material precluded unexposed tensile testing.

TABLE XI. - CONCLUDED.

Alloy	Rig environment	Rig exposure time, hr	0.2 percent offset yield strength, MPa	Ultimate tensile strength, MPa	Elongation, percent
Inconel 718(wd)	Unexposed Helium Hydrogen	555 565	464 375 233	519 459 339	b1 9 42 58
Inconel 718(a)	Unexposed Helium Hydrogen	1480 2100	526 254 267	540 302 318	25 62 54
Inconel 750	Unexposed Helium Hydrogen	1060 1495	399 130 172	404 284 260	21.5 40 
Pyromet 901	Unexposed Helium Hydrogen	3500 3500	451 230 181	512 289 300	24 12 19
HS-188	Unexposed Helium Hydrogen	1463 2326	359 270 305	397 349 342	<sup>b</sup> 50 44 43

<sup>a</sup>Average of two tests except where noted.
<sup>b</sup>Single test.
<sup>c</sup>Lack of sufficient material precluded unexposed tensile testing.

TABLE XII. - TENSILE PROPERTIES OF THE CG-27 TUBING BEFORE AND AFTER ENDURANCE TESTING FOR 3500 hr AT 21.6 MPa IN EITHER  $\rm H_2$  + 1%  $\rm CO_2$  or He at 820° C

Rig environment	Rig exposure time, hr	0.2 percent offset yield strength, MPa	Ultimate tensile strength, MPa	Elongation, percent		
		25° C	<b>.</b>	<u> </u>		
Unexposed He H <sub>2</sub> + 1% CO <sub>2</sub>	3500 3500	899 576 551	1364 820 787	14.5 2.8 2.3		
		820° C				
Unexposed He H <sub>2</sub> + 1% CO <sub>2</sub>	3500 3500	363 272 273	529 355 346	14 32.9 29.5		

TABLE XIII. - SUMMARY OF RESULTS OF TENSILE PROPERTIES OF 820° C ENDURANCE TESTED TUBES IN EITHER H2 + 1% CO2 or He

Alloy	Rig environment	Average rupture	Permeability coefficient,	Tensile property change as percent of as-received properties							
time, hr		time,	¢, after 250 hr exposure x 10 <sup>-6</sup> cm <sup>2</sup> /sec MPa	15 MPa - 820° C				21 MPa - 820° C			
				Ultimate strength		Elongation percent		Ultimate strength		Elongation percent	
				RT	820° C	RT	820° C	RT	820° C	RT	820° C
N-155	He H <sub>2</sub>	606 1240	0.37	-11 -13	-16 -13	-24 (a)	+135 +104				
A-286	He H <sub>2</sub>	399 419	.57	-20 -25	-12 -14	-70 -78	+72 +52				
Incoloy 800	He H <sub>2</sub>	118 c130R	.76 (100 hr)	+3 -0.1	-0.01 .06	-23 -56	-14 -16				
19-9DL	He H <sub>2</sub>	601 601	5.05	-32 -45	-31 -20	(a) -92	-31 -47				
CG-27	He H2	<sup>C</sup> 3500R 3500R	.13	-44 -46	-28 -33	-45 -38	204 118	-40 -42	-33 -35	-81 -84	+135 +111
W-545	He H <sub>2</sub>	2777 2372	3.80	-45 -74	-64 -38	-75 -91	(a) -78				
12RN72	He H <sub>2</sub>	1598 c <sub>3500R</sub>	.31	(b)	(b)	(b)	(b) (b)				
12RN72(cw)	He H <sub>2</sub>	1374 1200	.18	(b)	(b)	(b)	(b)				
253MA	He H <sub>2</sub>	1273 c <sub>2099R</sub>	2.47	-16 -5	-17 -10	-65 -58	-20 +16				
Sanicro 31H	He H <sub>2</sub>	154 c <sub>165R</sub>	.99 (100 hr)	5 +.3	-1 -10	-46 (a)	-22 -27				
Sanicro 32	He H <sub>2</sub>	878 c <sub>2919R</sub>	.85	-7 -42	(a) -7	(a) -95	(a) (a)		<del>-</del>		
Inconel 601		567 ¢890R	.15	-19 -12	+1 -3	+5 +12.5	16 14				
Inconel 625	He H <sub>2</sub>	2856 c <sub>3500R</sub>	.33	+3 -3	+13 +11	-41.5 (a)	(a) (a)		<b>-</b>		
Inconel 718(wd)	He H <sub>2</sub>	514 765	.15	+9 +2	-12 -35	-30 -38	+121 +205				
Inconel 718(a)	He H <sub>2</sub>	1672 1925	.23	-20 -27	-44 -41	-51 (a)	+148 +108				
Inconel 750	He H <sub>2</sub>	796 570	.18	-30 -54	-30 -36	-73 -78	+86 (a)		 		
Pyromet 901	He H <sub>2</sub>	c <sub>3500R</sub> c <sub>3500R</sub>	.064	-10 -52	-44 -41	-73 -78	-50 -21				
HS-188	He H <sub>2</sub>	1392 1785	.69	-13 -6	-12 -16	(a) (a)	-12 -14				

<sup>&</sup>lt;sup>a</sup>Broke outside gage mark. <sup>b</sup>Insufficient material for unexposed tensile test. <sup>c</sup>Tube removed from rig prior to rupture.






Figure 1. - Microstructures of hairpin tubes before and after rig exposure.








Figure 1. - Continued.






Figure 1. - Continued.








Figure 1. - Continued.




Figure 1. - Concluded.




Figure 2. - Hairpin test specimen (not to scale).




Figure 3. - Test module for Stirling engine simulator materials test rig.




Figure 4. - Schematic representation of Stirling engine simulator materials test rig.




Figure 5. - Temperature profile in Stirling simulator engine test.




Figure 6. - Tube tensile specimen and grips.




Figure 7. – Apparent hydrogen permeability coefficient  $\Phi$  versus rig exposure time for iron base alloys tested at  $820^0$  C with H $_2$  + 1% CO $_2$  at 15 MPa.




Figure 8. – Apparent hydrogen permeability coefficient  $\Phi$  versus rig exposure time for nickel base alloys tested at 820 $^{\!0}$  C with H $_2$  + 1% CO $_2$  at 15 MPa.




Figure 9. - Apparent hydrogen permeability coefficient  $\Phi$  versus rig exposure time for cobalt-base alloy HS-188 tested at  $820^{\circ}$  C with H<sub>2</sub> + 1% CO<sub>2</sub> at 15 MPa.




Figure 10. – Apparent hydrogen permeability coefficient for CG-27 as a function of rig exposure time. Temperature,  $820^{\circ}$  C.




Figure 11. - Ranking of hairpin tubes according to rupture lives when pressurized with 15 MPa helium at 820° C.




Figure 12. - Modules with normal and defective heat-shield.





Figure 13. - Room temperature tensile properties of tubing before and after endurance testing at  $820^{\circ}$  C for 3500 hr and at 15 MPa. (No "unexposed" tensile tests were performed on 12RN72 tubes because of lack of material.)






Figure 14. - 820<sup>o</sup> C tensile properties of tubing alloys before and after endurance testing at 820<sup>o</sup> C for 3500 hr and at 15 MPa. (No "exposed" tensile tests were performed on 12RN72 tubes because of lack of material.)




Figure 15. - Tensile properties of CG-27 before and after endurance testing for 3500 hr at 21 MPa and at  $820^{\rm O}$  C.




Figure 16. - Apparent hydrogen permeability coefficient at 250 hr for tubing material endurance tested at 820° C and 15 MPa.

1. Report No. NASA TM-83782	2. Government Accessio	n No.	3. Recipient's Catalog	No.				
			5. Report Date					
4. Title and Subtitle			•					
Evaluation of Candidate S	tirlina Engine He	ater Tube	October 198	4				
Alloys after 3500 Hours E			6. Performing Organiza	tion Code				
	xposure to night	ressure		111011 0006				
Doped Hydrogen or Helium			778-35-03					
7. Author(s)			8. Performing Organiza	tion Report No.				
, , , , , , , , , , , , , , , , , , , ,			E-2276					
John A. Misencik and Robe	rt W. Titman		L-2270					
donn A. Misencik and Robe	r c II. II craii	-	0. Work Unit No.					
		'	O. WORK OTHER NO.					
9. Performing Organization Name and Address		. l	1. Contract or Grant No	<del></del>				
National Aeronautics and	space Administrat	10n		<b>-</b> .				
Lewis Research Center								
Cleveland, Ohio 44135		l <sub>1</sub>	3. Type of Report and F	Period Covered				
	<del>.</del>		Technical Memorandum					
12. Sponsoring Agency Name and Address			rechnical Me	emorandum				
U.S. Department of Energy		-		one Donout No				
Office of Vehicle and Eng	ine R&D	1		coe∈Report No.				
Washington, D.C. 20545			DOE/NASA/510	040-56				
15. Supplementary Notes	· · · · · · · · · · · · · · · · · · ·							
Final manage Propagad	ndan Intanaganay	Agroomont DE Al	101 770051040					
Final report. Prepared u	nder Interagency	Agreement DE-A	101-776351040	•				
16. Abstract								
The heater head tubes of o	rurrent prototype	automotive Sti	irlina enaines	s are fabri-				
cated from alloy N-155, a								
United State imports over								
resource supplies could no								
cobalt in the heater head								
imperative that substitute								
described herein focused of			• • • • • • • • • • • • • • • • • • • •	•				
substitutes plus the 20 pe								
wall tubing in the NASA Le								
fuel fired test rigs. Tul	oes filled with e	ither hydrogen	doped with 1	percent CO <sub>2</sub>				
or with helium at a gas pr	essure of 15 MPa	and a temperat	cure of 820° (	C were cyclic				
endurance tested for times	s up to 3500 hr.	Results showed	d that two ire	on-nickel				
base superalloys, CG-27 ar	nd Pyromet 901 su	rvived the 3500	) hr endurance	e test. The				
remaining alloys failed by								
eral other alloys had supe								
the hydrogen working fluid								
hydrogen permeability thro				caucing				
	Augus and the shift	, 00000 11140001	4000					
	<del></del>	40.00.17.00.00.00.00						
17. Key Words (Suggested by Author(s))	18. Distribution Statemen							
Stirling engine; Permeation	Unclassified	Unclassified - unlimited						
Rupture; Tensile	STAR Category 26							
	DOE Category UC-25							
		DOE Category	UC-25					
19. Security Classif. (of this report) Unclassified	20. Security Classif. (of this	DOE Category		22. Price*				